Exhibit B

Site	Address	City	State	EMV Brand Compliant	# of Dispensers		EMV Costs	Inv	roices sent to BB	l	voices sent to B (8/22/24)
IL0084	931 E. Roosevelt	Lombard	IL	No	2	\$	102,797.00	\$	-	\$	-
IL0097	3321 W Algonquin Rd	Rolling Meadows	IL	No	8	\$	119,388.00	\$	1,715.00	\$	-
LA0053	12392 Plank Rd	Baton Rouge	LA	no	2	\$	-			\$	-
LA0054	12567 Florida Blvd	Baton Rouge	LA	no	2	\$	-			\$	-
LA0057	1648 Pitkin Rd	Leesville	LA	no	1	\$	-			\$	-
LA0058	1330 Plank Rd	Baton Rouge	LA	No	6	\$	-			\$	-
LA0060	1764 N Parkerson Ave	Crowley	LA	Yes	N/A	\$	-			\$	-
MI0001	501 W Washington St	Marquette	MI	Yes	N/A	\$	-	\$	20,544.09	\$	14,067.66
MI0002	405 N Stephenson Ave	Iron Mountain	MI	Yes	N/A	\$	-	\$	27,547.94	\$	-
MN0002	407 E Blue Earth Ave	Fairmont	MN	Yes	N/A	\$	-			\$	-
MN0006	624 S Minnesota Ave	St. Peter	MN	Yes	N/A	\$	-			\$	-
MN0008	3017 1st Ave	Hibbing	MN	no	2	\$	-			\$	-
MN0009	100 W Lake St	Chisholm	MN	No	2	\$	-			\$	-
MN0010	202 S 8th St	Virginia	MN	Yes	N/A	\$	-	\$	28,535.00	\$	1,634.75
MN0018	920 Mankato Ave	Winona	MN	Yes	1 - Subway	\$	-	\$	43,780.93	\$	9,453.16
MN0023	7600 University Ave NE	Fridley	MN	Yes	N/A	\$	-			\$	-
MN0025	301 4th St	International Falls	MN	Yes	N/A	\$	-	\$	54,045.23	\$	-
MN0026	1709 2nd Ave	International Falls	MN	Yes	N/A	\$	-	\$	18,636.36	\$	-
MN0030	4140 Berkshire Ln N	Plymouth	MN	Yes	N/A	\$	-			\$	-
MN0039	5995 Hodgson Rd	Shoreview	MN	Yes	N/A	\$	-	\$	14,741.48	\$	1,673.40
MN0041	2020 St. Croix Trail S	Lake St. Croix Beach	MN	no	1					\$	-
MN0045	4221 Haines Rd	Hermantown	MN	Yes	N/A	\$	-	\$	14,052.85	\$	-
MS0004	1724 University Ave	Oxford	MS	No	6	\$	-			\$	-
MS0005	1802 East University Ave	Oxford	MS	No	4	\$	-			\$	-
OH0030	1550 QUEEN CITY AVE	CINCINNATI	ОН	Yes	N/A	\$	-			\$	-
OH0036	1326 HOPPLE STREET	CINCINNATI	ОН	Yes	N/A	\$	-			\$	-
OH0048	9171 UNION CENTRE BLVD	WEST CHESTER	ОН	Yes	N/A	\$	-			\$	-
OH0077	8200 COLUMBIA ROAD	OLMSTED FALLS	ОН	no	4	\$	-	\$	9,261.00	\$	9,078.00
OH0088	10300 Brookpark Road	Brooklyn	ОН	Yes	N/A	\$	-			\$	7,670.62
OH0095	32393 LORAIN ROAD	NORTH RIDGEVILLE	ОН	Yes	N/A	\$	-			\$	59,863.00
OH0100	30812 DETROIT ROAD	WESTLAKE	ОН	Yes	N/A	\$	-			\$	-
SD0002	225 W Kemp Ave	Watertown	SD	No	N/A	\$	-			\$	-
SD0004	512 S Sanborn St	Mitchell	SD	No	N/A	\$	-			\$	-
VA0452	702 E Atlantic St	South Hill	VA	Yes	N/A	\$	-			\$	-
WI0003	237 Keller Ave S	Amery	WI	Yes	N/A	\$	-	\$	26,253.80	\$	-
WI0005	1040 Bergslien St.	Baldwin	WI	Yes	N/A	\$	-	\$	10,558.95	\$	16,269.62
WI0010	311 Belknap St	Superior	WI	Yes	N/A	\$	-			\$	-
WI0054	1 Hewett St	Neillsville	WI	Yes	N/A	\$	_	\$	7,624.05	\$	3,316.92
WI0057	706 N 4th St	Tomahawk	WI	Yes	N/A	\$	_	\$	14,318.19	\$	-
WI0062	100 Second St	Hudson	WI	Yes	N/A	\$	-	\$	40,108.69	\$	-
WI0063	406 Belknap St	Superior	WI	Yes	N/A	\$	-	\$	19,958.19	\$	-
					<u> </u>	H	222,185.00	'	351,681.75	\$	123,027.13
		•					-	_	TAL	\$	696,893.88



Galaxu Group

GALAXY FMS 201 S Blakely Street, Suite 251 Dunmore, PA 18512 Phone # 888-689-3487 Fax # 888-689-3492 https://galaxyfms.com/

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

Invoice # 210479

Invoice Date 2/28/2024 Due Date 3/9/2024 Our W/O # 114576 Order Type General

Category Construction

PO # IYS-MSO-LC-WI0062

SERVICE LOCATION

Joe's Kwik Mart - Loc # WI0062 100 Second St Hudson, WI 54016 Phone #

JOB DESCRIPTION

Exterior:

Furnished and installed 7 soffit lights with LED direct wire lamps and disposed of lamps and ballast.

Furnished and installed 2 Cree gas Canopy Lights.

Furnished and installed 1 parking lot light with new LED Direct drive lamp- (Assumes power is to pole base.)

Interior:

Furnished and installed 40-4' T-8 lamps and ballast on the sales floor as required.

Furnished and installed 30-2' T-8 lamps and ballast on the sales floor as required.

Furnished and installed 1-6' T12 single-pin lamps for cooler doors.

Furnished and installed 4 AC filters.

Furnished and installed a new soap dispenser.

Furnished and installed 10 stained ceiling tiles.

Qty	Description	Man Hour	Unit Price	Total Tax
1	As Per SOW Above		35,863.36	35,863.36

NET 10	Subtotal	35,863.36
Please Remit Payment To:	Tax 0 %	0.00
Galaxy Group, LLC	Total	35,863.36
471 N Broadway Suite 215 Jericho, NY 11753	Balance	35,863.36



GALAXY FMS
201 S Blakely Street, Suite 251
Dunmore, PA 18512
Phone # 888-689-3487 Fax # 888-689-3492
https://galaxyfms.com/

Invoice # 210462

Invoice Date 2/28/2024

Due Date 3/9/2024

Our W/O # 114451

Order Type General

Category Construction

PO # IYS-MSO-LC-WI0063

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

SERVICE LOCATION

Joe's Kwik Mart - Loc # WI0063 406 Belknap Superior, WI 54880 Phone #

JOB DESCRIPTION

Storage Room:

Furnished and installed 6 T-8 lamps and 3 ballast.

Restrooms:

Furnished and installed 6 T-8 Lamps

Exterior:

Furnished and installed lamps in 2 under canopy fixtures. Furnished and installed lamps in 10 under soffit fixtures. Furnished and installed lamps in 1 parking lot light. Furnished and installed New in use cover for 1 exterior outlet. Furnished and installed New Cover for E-stop.

rumished and installed New Cover for E-stop.

Interior:

Furnished and installed Bakery Case lamp.
Furnished and installed Beer Cooler (1) lamp.
Furnished and installed Main Cooler (11) lamps.
Furnished and installed Main Store Floor (153) T-:

Furnished and installed Main Store Floor (153) T-8 lamps and 10 ballast.

Water Heater:

Removed and disposed Water Heater Furnished and installed New Water Heater Furnished and installed Wire to New Water Heater

Total Tax	Man Hour Unit Price	y Description
19,958.19	19,958.19	Labor & Material
19,958.19	Subtotal	NET 10
0.00	Tax 0 %	Please Remit Payment To;
19,958.19	Total	Galaxy Group, LLC
19,958.19	Balance	171 N Broadway Suite 215 Jericho, NY 11753
	Balance	Suite 215



GALAXY FMS 201 S Blakely Street, Suite 251 Dunmore, PA 18512 Phone # 888-689-3487 Fax # 888-689-3492 https://galaxyfms.com/

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

Invoice # 211304

Invoice Date 4/9/2024 Due Date 4/19/2024 Our W/O # 114492 Order Type General Category Construction

PO # IYS-MSO-LC-WI0054

SERVICE LOCATION

Joe's Kwik Mart - Loc # W10054 1 Hewett St Neillsville, WI 54456 Phone #

JOB DESCRIPTION

Store Maintenance - 2/1 @9:00 am

Inspected Heating System (Heat Not Working)

Inspecedt Air Conditioning Inspected Roofing for issues

Inspected compressor for walk in cooler not working (or working well)

Replaced broken Perimeter Lights

Furnished & Instaled new Ceiling tiles to replace stained ones

Qty	Description	Man Hour	Unit Price	Total Tax
1	Labor and Material		7,136.37	7,136.37

Tax 0 %	0.00
Total	7,136.37
Balance	7,136.37
	Total



Galaxu Group

GALAXY FMS 201 S Blakely Street, Suite 251 Dunmore, PA 18512 Phone # 888-689-3487 Fax # 888-689-3492 https://galaxyfms.com/

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

Invoice # 211303

Invoice Date 4/9/2024 Due Date 4/19/2024 Our W/O # 114493 Order Type General Category Construction PO # IYS-MSO-LC-WI0057

SERVICE LOCATION

Joe's Kwik Mart - Loc # WI0057 706 North 4th St Tomahawk, WI 54487 Phone #

JOB DESCRIPTION

General Conditions: Mobilization Site Supervision Project Management Dumpsters General Labor Day to Day Cleaning & Final Clean Equipment Rental Insurance 0 & P

Store Maintenace:

Furnished and installed 68 interior 4100K lamps on main sales floor. Furnished and installed 4 interior lamps in Storage Room. Furnished and installed 6 interior lamps in the back mechanical room. Furnished and installed 1 T-8 tombstone above bakery items. Furnished and installed 9-Cooler Lights t-12 F72. Furnished and installed 4 exterior Soffit lights. Furnished and installed 11 interior Ceiling tiles. Furnished and installed non-working LED canopy Light.

Furnished and installed Women's exhaust fan.

Clarifications:

This price proposal includes Supervision and Removal of all debris from the work site. All work is to be done during normal business hours (7 am-5 pm) with non-union labor. Permits, Construction Drawings, Civil Engineer, and/or Bonds are not included. All work is based on existing conditions and doesn't include costs for unseen and new arising issues/conditions. This proposal is an all-in cost for the above SOW. If any SOW is added or deleted, Galaxy Group

reserves the right to re-evaluate and re-price the new SOW.

Excluded:

All Exterior Work is Excluded Fire Sprinkler and any necessary shutdowns are NIC Fire Panel, Alarms, and Tie Ins are NIC Permits, Bonds, New Construction Drawings, Civil or Structural Engineering, is NIC Rodent Control or Exterminating is NIC

Print Date: 04/09/2024 Net 10 Days Page 1 of 2



Galaxy Group

GALAXY FMS 201 S Blakely Street, Suite 251 Dunmore, PA 18512 Phone # 888-689-3487 Fax # 888-689-3492 https://galaxyfms.com/

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

Invoice # 211303

Invoice Date 4/9/2024 Due Date 4/19/2024 Our W/O # 114493 Order Type General

Category Construction

PO # IYS-MSO-LC-WI0057

SERVICE LOCATION

Joe's Kwik Mart - Loc # WI0057 706 North 4th St Tomahawk, WI 54487 Phone #

Union Labor or After hours (Premium Time) is NIC Anything not called out in above SOW is NIC

Qty	Description	Man Hour	Unit Price	Total Tax
1	Labor and Materials		14,318.19	14,318.19

	14,318.19
Tax 0 %	0.00
Total	14,318.19
Balance	14,318.19
	Total



Golaxy Group

GALAXY FMS 201 S Blakely Street, Suite 251 Dunmore, PA 18512 Phone # 888-689-3487 Fax # 888-689-3492 https://galaxyfms.com/

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

Invoice # 210481

Invoice Date 2/28/2024 Due Date 3/9/2024 Our W/O # 114450 Order Type General Category Construction

PO # IYS-MSO-LC-WI0005

Page 1 of 1

SERVICE LOCATION

Joe's Kwik Mart - Loc # WI0005 1040 Bergslien St Baldwin, WI 54002 Phone #

JOB DESCRIPTION

Store Maintenance

Inside Store:

Furnished and installed an estimated (20) T8 lamps. Furnished and installed an estimated (4) T8 ballasts. Furnished and installed an estimated (10) cooler lamps.

Outside Store:

Repaired (3) pole light fixtures that are out.

LABOR an	d MA	MTER	IALS	٨.
----------	------	------	------	----

Qty	Description	Man Hour	Unit Price	Total Tax
1	Labor and Material		8,181.82	8,181.82

Subtotal	8,181.82
Tax 0 %	0.00
Total	8,181.82
Balance	8,181.82
	Tax 0 % Total

Print Date: 02/28/2024 Net 10 Days



GALAXY FMS
201 S Blakely Street, Suite 251
Dunmore, PA 18512
Phone # 888-689-3487 Fax # 888-689-3492
https://galaxyfms.com/

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

Invoice # 210492

Invoice Date 2/29/2024
Due Date 3/10/2024
Our W/O # 114453
Order Type General
Category Construction

PO # IYS-MSO-LC-WI0003

SERVICE LOCATION

Joe's Kwik Mart - Loc # WI0003 237 Keller Ave S Amery, WI 54001 Phone #

JOB DESCRIPTION

Inside Work:

Furnished and installed an estimated (70) T8 lamps. Furnished and installed an estimated (15) T8 ballasts. Furnished and installed an estimated (10) cooler lamps.

Outside Work:

Repaired (3) pole lights that were out.

Repaired soffit light.

Qty	Description	Man Hour	Unit Price	Total Tax
1	Labor and Material		26,253.80	26,253.80
			4340333	1216221104

Subtotal	26,253.80
Tax 0 %	0.00
Total	26,253.80
Balance	26,253.80
	Tax 0 % Total

Christopher Rosewell

6924 Hollywood Dr. Parma OH 44129 Phone 216-650-6596 DATE: Invoice #: February 29, 2024 031224-CAP

BILL TO:

FOR:

Olmsted Falls

Violations Phase 1

CAP

Att: Nolan Lockner 645 Hamilton St Suite 400 Allentown, PA 18101

Store #	Address	CITY	Description	Amount
ОН0077	8200 Columbia Rd	Rd Olmsted Falls Fix All Uneven Pavers Along Columbia Rd (Per City) \$		\$ 450.00
			Fix and Replace 4 sections of Fence behind Car Wash (per city)	\$ 1,350.00
1			Trim 15 Large Bushes Along North Side of Car Wash (per city)	\$ 800.00
			Remove 6 Large Trees and several smaller trees Along West side of Car Wash	\$ 2,400.00
			Remove all dead, broken and overgrown bushes/trees directly behind building	\$ 1,750.00
			Remove bushes along sidewalk on east side of property (per city)	\$ 625.00
			Clean-up Vines, cut 3 medium trees on West side of lot growing over business	\$ 825.00
and the second	Activity of the second		Clean up all leaves, branches, remove all remaining dead bushes throughout lot	\$ 375.00
otal due	within 30 Days	65.00	SUB TOTAL	\$ 8,575.00
Il Checks	Made Payable t	o Christophe	r Rosewell SALES TAX 8%	686.00
	A CONTRACTOR OF THE PROPERTY O	A REAL PROPERTY.	TOTAL IF PAID BY 04/12	\$ 9.261.00

| SALES TAX 8% | \$ 686.00 | | TOTAL IF PAID BY 04/12 | \$ 9,261.00 | | 15% Late Charge if not paid within 30 Days | Total IF PAID AFTER 04/12 | \$ 10,650.15

THANK YOU FOR YOUR BUSINESS!



GALAXY FMS

201 S Blakely Street, Suite 251 Dunmore, PA 18512

Dunmore, PA 18512

Phone # 888-689-3487 Fax # 888-689-3492

https://galaxyfms.com/

Invoice # 210269

Invoice Date 2/14/2024

Due Date 2/24/2024 Our W/O # 114452

Order Type General

Category Construction

PO # IYS-MSO-LC-MN0045

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

SERVICE LOCATION

Joe's Kwik Mart - Loc # MN0045 4221 Haines Rd Hermantown, MN 55811 Phone #

JOB DESCRIPTION

Store Maintenance:

- Supplied and replaced 4 broken bulbs for Pole Lighting on the perimeter with LED Corn Cobs (Used bucket truck).
- Supplied and replaced 90 interior lights with fluorescent bulbs.
- Supplied and replaced cooler lights with fluorescent lights.
- Supplied and replaced ballast and T-8 fluorescent lamps.
- Supplied and replaced 2 exterior can lights with new ballast and lamps.

Qty	Description	Man Hour	Unit Price	Total Tax
1	Labor & Material		13,065.46	13,065.46

Subtotal	13,065.46
Tax 0 %	0.00
Total	13,065.46
Balance	13,065.46
	Tax 0 % Total



GALAXY FMS
201 S Blakely Street, Suite 251
Dunmore, PA 18512
Phone # 888-689-3487 Fax # 888-689-3492
https://galaxyfms.com/

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

Invoice # 210493

Invoice Date 2/29/2024
Due Date 3/10/2024
Our W/O # 114575
Order Type General
Category Construction
PO # IYS-MSO-LC-MN0010

SERVICE LOCATION

Joe's Kwik Mart - Loc # MN0010 202 8th St S Virginia, MN 55792 Phone #

JOB DESCRIPTION

Inside Work:

Furnished and installed 20 - T-8 Lamps and Ballasts on Sales Floor.

Furnished and installed 2 -8 T12 Lamps in BOH

Furnished and installed 7 - 5 T12 Single Pin Lamps for Cooler Doors

Furnished and installed Jelly Jar Light inside of Cooler.

Furnished and installed new tile on Sales floor in two (2) locations.

Outside Work:

Furnished and installed 2 wall pack light fixtures on exterior of location.

Furnished all labor and materials to repair one (1) Parking Lot Light with New LED Direct Drive Lamp.

Furnished all labor and materials to repair siding with Aluminum Flashing and Flat Panel Aluminum to cover the damaged siding.

Qty Description Man Hour Unit Price Total Tax 1 Labor and Materials 28,535.00 28,535.00

Subtotal	28,535.00
Tax 0 %	0.00
Total	28,535.00
Balance	28,535.00
	Tax 0 % Total



GALAXY FMS
201 S Blakely Street, Suite 251
Dunmore, PA 18512
Phone # 888-689-3487 Fax # 888-689-3492
https://galaxyfms.com/

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

Invoice # 211305

Invoice Date 4/9/2024
Due Date 4/19/2024
Our W/O # 114489
Order Type General
Category Construction

PO # IYS-MSO-LC-MI0001

SERVICE LOCATION

Joe's Kwik Mart - Loc # MI0001 501 W Washington St Marquette, MI 49855 Phone #

JOB DESCRIPTION

Store Maintenance - 2/1 @9:00am

Repaired Interior lights out.
Repaired Soffit light out (building front)
Checked the walk-in cooler condenser; it keeps stopping.
Repaired hand sink and removed urinal as per LC's Direction

LABOR and MATERIALS

Qty	Description	Man Hour	Unit Price	Total Tax
1	As Per Above SOW		19,069.09	19,069.09

Subtotal	19,069.09
Tax 0 %	0.00
Total	19,069.09
Balance	19,069.09
	Tax 0 % Total

Print Date: 04/09/2024



Invoice

Date	Invoice #
3/26/2024	26160

Bill To	Location	
Cross America Partners 645 Hamilton Street, Suite 400 Allentown, PA 18101	920 MANKATO AVE	

	Work Order	P.O. No.	Terms	Rep
	8995		Net 30	
Labor/Work Descript	ion			Amount
REPLACE WITH PANA REPLACE 2 HORIZON' INSTALL 2 BRYANT 92 FURNACES HAVE 2 ST HIGH FIRE 117K BTU'S ECM VARIABLE SPEE! REPLACE 2 CENTRAL BRYANT MODEL 1130 R-410 REFRIGERANT 3 PHASE, 5 TON UNITS 13 SEER REPLACE 2 HORIZON' REPLACE DETERIORA	I'S AND WOMEN'S BATH. ASONIC ULTRA SILENT FAL FURNACES ABOVE 26TC120V24 96.7% EFFICE FAGE GAS VALVE S LOW FIRE 76K BTU'S D BLOWER MOTOR. A/C UNITS. 60 S. FAL CASED A COILS FOR ATTING BLACK GAS PIPIN BOTH SUBWAY AND THE D EQUIPMENT	COOLERS. SIENT 2 STAGE FURNACE R COOLING. G IN CAR WASH AREA. HE GAS STATION. MN0018 CAPEX GL 6000 Dallas O 3/27/24	0 HVAC	Approved by Lisa
			To	otal \$39,700.00



GALAXY FMS

201 S Blakely Street, Suite 251

Dunmore, PA 18512

Phone # 888-689-3487 Fax # 888-689-3492

https://galaxyfms.com/

Invoice # 210543
Invoice Date 3/4/2024

Due Date 3/14/2024

Our W/O # 114399

Order Type General

Category Refrigeration

PO#

SERVICE LOCATION

Arbo Gass - Loc # IL0097 3321 W Algonquin Rd Rolling Meadows, IL 60008 Phone #

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

JOB DESCRIPTION

Initial trip

- -Arrived on site met with workers on site
- -Assessed the walk in cooler temping at 48 degrees
- -Did a full thorough assessment to confirm no leakage or damage was done to the (2) RTUs on roof
- -No damage to the RTUs after troubleshoot
- -Determined door sweep has to be installed
- -Sourced material

Return Trip

- -Supplied and installed (1) new refrigerator door sweep
- -Allowed walk in cooler to get to required temperature
- -Removed and disposed of debris

LABOR and M	IATERIALS
-------------	-----------

Qty	Description	Man Hour	Unit Price	Total Tax
2	Labor	6.00	115.00	1,380.00
1	Material Door sweep for refrigerator		185.00	185.00
2	Trip Charge		75.00	150.00

NET 10	Subtotal	1,715.00
Please Remit Payment To:	Tax 0 %	0.00
·	Total	1,715.00
Galaxy Group, LLC 471 N Broadway Suite 215	Balance	1,715.00
Jericho, NY 11753		



Cross America PartnersInvoice ID:9765.01600 Hamilton StreetInvoice Date:03-27-2024Suite 500Draw ID:1Allentown, PA 18101Customer ID:30860

Job Location:

IL0084 Dispenser Replacement 931 East Roosevelt Rd Lombard, IL

NET 10 DAYS

Remit to: P.O. Box 5946 Rockford, IL 61125

Description Item Amount 1 Remove six existing Wayne Vista dispensers. Install (6) new Wayne Ovation 2 dispensers and new hanging hardware. Installation completed on 3/8. 2 (6) Wayne Ovation Dispensers and Tax 80,865.00 3 Dispenser Freight 2,250.00 4 Dispenser removal and installation 15,572.00 5 Hanging Hardware 4,110.00

AMOUNT DUE \$102,797.00

A finance charge of 1-1/2% per month, which is an annual percent of 18%, will be added to all amounts not paid within 30 days from the billing date.

Carla Bautista

From: Randy Kehs

Sent: Wednesday, March 27, 2024 11:56 AM

To: CAP AP Subject: IL0084

Attachments: 9765.01 invoice.pdf

FM CAPX RK0192 APPROVED

Randy Kehs Wholesale Operations Manager 484-201-7831 (Cell)

Cross America Partners 645 Hamilton Blvd. Suite 400 Allentown PA 18101



From: Sasha Kirchner <SashaK@rstenstrom.com> Sent: Wednesday, March 27, 2024 10:17 AM

To: Randy Kehs <rkehs@caplp.com>

Subject: invoice 9765.01

Remove six existing Wayne Vista dispensers. Install (6) new Wayne Ovation 2 dispensers and new hanging hardware. Installation completed on 3/8.

\$102,797.00 Total

Sasha Kirchner

Project Administrative Assistant Stenstrom Petroleum Services Group

2422 Center Street, Rockford, IL 61108

p. 815-398-6250 | Toll Free: 1-800-841-5582





CONFIDENTIALITY NOTICE: The information in this email is confidential, may be privileged, and is only for the use of the recipient named above. If you are not the intended recipient, you are hereby notified that distribution of this email is neither intended nor permissible. If you have received this email by mistake, please notify the sender immediately by telephone, email, or fax, and destroy all printed and electronic copies of this email.



Cross America PartnersInvoice ID:9770.01600 Hamilton StreetInvoice Date:03-27-2024Suite 500Draw ID:1Allentown, PA 18101Customer ID:30860

Job Location:

IL0097 Marathon Dispensers 3321 West Algonquin Rd Rolling Meadows, IL

NET 10 DAYS

Remit to: P.O. Box 5946

Rockford, IL 61125

Item	Description	Amount
1	Remove 7 existing dispensers. Install (6) new Ovation 2 blending dispensers and (1) Ovation single product diesel dispenser. Install all new hanging hardware.	
2	(6) Ovation 2 three product blends and (1) Ovation 2 single product diesel	87,462.00
<i>3</i>	Installation Hanging Hardware	17,290.00 4,795.00
5	Freight	2,625.00
6	tax	7,216.00

AMOUNT DUE \$119,388.00

A finance charge of 1-1/2% per month, which is an annual percent of 18%, will be added to all amounts not paid within 30 days from the billing date.

Carla Bautista

From: Randy Kehs

Sent: Wednesday, March 27, 2024 9:51 AM

To: CAP AP Subject: IL0097

Attachments: 1invoice 9770.01.pdf

FM CAPX RK0191 APPROVED

Randy Kehs Wholesale Operations Manager 484-201-7831 (Cell)

Cross America Partners 645 Hamilton Blvd. Suite 400 Allentown PA 18101



From: Sasha Kirchner <SashaK@rstenstrom.com> Sent: Wednesday, March 27, 2024 9:28 AM

To: Randy Kehs <rkehs@caplp.com> **Subject:** RE: invoice 9770.01 revised

Hi, sorry yesterday I noticed the invoice I originally sent was to the wrong address . This is revised invoice . Thanks

Sasha Kirchner

Project Administrative Assistant Stenstrom Petroleum Services Group

2422 Center Street, Rockford, IL 61108

p. **815-398-6250** | Toll Free: **1-800-841-5582**





CONFIDENTIALITY NOTICE: The information in this email is confidential, may be privileged, and is only for the use of the recipient named above. If you are not the intended recipient, you are hereby notified that distribution of this email is neither intended nor permissible. If you have received this email by mistake, please notify the sender immediately by telephone, email, or fax, and destroy all printed and electronic copies of this email.

From: Sasha Kirchner <SashaK@rstenstrom.com>

Sent: Tuesday, March 26, 2024 3:42 PM

To: rkehs@caplp.com

Cc: John Burke < John Bu@rstenstrom.com >

Subject: invoice 9770.01

Invoice for Remove 7 existing dispensers. Install (6) new Ovation 2 blending dispensers and (1) Ovation single product diesel dispenser. Install all new hanging hardware. See attached . 119,388.00

Sasha Kirchner

Project Administrative Assistant Stenstrom Petroleum Services Group

2422 Center Street, Rockford, IL 61108

p. **815-398-6250** | Toll Free: **1-800-841-5582**







CONFIDENTIALITY NOTICE: The information in this email is confidential, may be privileged, and is only for the use of the recipient named above. If you are not the intended recipient, you are hereby notified that distribution of this email is neither intended nor permissible. If you have received this email by mistake, please notify the sender immediately by telephone, email, or fax, and destroy all printed and electronic copies of this compiler.

L&D Maintenance, Inc.

13877 17th St. North Stillwater, Minnesota 55082 Phone: 651-303-4747

651-337-1118

Fax:

Michael Hejduk 4-1-2024 MN0039-5510 BM Other 60000

Invoice

DATE	INVOICE #
3/29/2024	2024-2050

BILL TO	
Cross America	

P.O. NUMBER	TERMS	REP	SHIP	VIA	F.O.B.	F.O.B. PI	
00020882							
QUANTITY	ITEM CODE		DESCRIP	TION	PRICE	EACH	AMOUNT
	L & M truck charge	Remove and rep 400.00 Fuel and truck e Tax included	lace Bath Fan Ma	aterials @ 87.48 lab		487.48	487.48 75.00
					Total		\$562.4
					Payments	/Credits	\$0.00
					Balanc	e Due	\$562.48

RE: **** Appointment not yet Accepted by Vendor ****

Michael Hejduk <mhejduk@caplp.com>

Wed 3/27/2024 12:51 PM

To:Idmaintenance@msn.com <Idmaintenance@msn.com>

0

Here is the ticket for the bathroom fan

Case# 00020882

Site: MN0039-5510

5995 Hodgson Road

Shoreview, MN 55126

Reported:

Men's bathroom fan not working.

Thanks,

Mike Hejduk

CAP Retail

330-518-6470

------ Original Message

From: No-Reply Address [noreply@crossamericapartners.com]

Sent: 3/27/2024, 1:47 PM

To: mhejduk@caplp.com

Subject: **** Appointment not yet Accepted by Vendor ****


Dear Michael,

Appointment #SA-7820 that was dispatched to Vendor MN0039-5510 an hour ago has not been accepted. Please follow up accordingly!

Link to Case: https://crossamericapartners.my.salesforce.com/5000p00000Fvu03IAB

Link to created Appointment: https://crossamericapartners.my.salesforce.com/500Qp00000Fvu03IAB If the appointment needs to be reassigned, please do so from the following link -





Sent from my iPhone



Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

INVOICE

Michael Hejduk 3-26-2024 WI0062-9505 C-Store 60038

> Invoice No.: Invoice Date: Client:

128054 03/26/2024 **CAP007**

AUT011-000045 Site: 1of 2

Page:

Service Location CROSS AMERICA (HUDSON-2ND ST) 100 SECOND ST HUDSON WI 54016-1504

Amount Due: \$343.56

P.O. #: Case# 00018844 Job Id: WESRS118269

Work Order Id: 203993 Completion Date: 03/13/2024

Work Requested:

CROSS AMERICA PARTNERS

Email Invoices: cap ap@capip.com 645 HAMILTON STREET, STE. 400 ALLENTOWN PA 18101

Freezer is not working - NTE 1500.00

Equipment: THREE DOOR FREEZER

Model Serial #:

RI-3-DFR-KT 989-4273-9

Work Performed:

Mar 12, 2024 - jtome Freezer was off upon arrival. The breaker for the fans lights solenoid and thermostat was off. Before I turned everything on I hook my gauges up to the compressor and there is pressure. I checked power at the contactor to make sure we had all three legs of power. I then pushed in the contactor to hear what the we had all three legs of power. I then pushed in the contactor to hear what the compressor sounded like. Compressor sounds like it is still intact and just off on low pressure. I turned the breaker on, solenoid was energized and compressor turned on. I let it run and watched the pressures. Pressures look a a little lower than I'd like it and sight glasses just barely flashing. I decided to add some freon, once I got to decent pressures I added about 2 lb of 404, sight glass is clear. After unit ran for about 15 minutes evaporator fans kicked on. As the temperature started coming down the fans turned off and on but once it got to about 15 degrees the fan stayed on. This tells me clicks on are working like they should. All evaporator fans are spinning the right direction and are not making any squealing noises or vibrating. Leak checked the whole system besides what went underground, leak checked at the compressor, and leak checked on the roof at the condenser. Did not find any leaks. I made sure to check all components such as thermostat, solenoid, low pressure switch, defrost clock, defrost heaters. I watched unit go into defrost and pump down and shut off. All heaters work. I watched unit come out of defrost and go back into Refrigeration. Unit came down to-10 and shut off on temp. Running like it should be. Unit came down to-10 and shut off on temp. Running like it should be.

Labor Charges

Ext'd Price

MN Technician Regular

03/12/2024

HRS.

2.00

@

\$111.0000

\$222.00









INVOICE



Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

> CROSS AMERICA PARTNERS Email Invoices: cap_ap@caplp.com 645 HAMILTON STREET, STE. 400 ALLENTOWN PA 18101

Invoice No.: 128054 Invoice Date: 03/26/2024 Client: CAP007 Site: AUT011-000045

Page: 2of 2

Service Location CROSS AMERICA (HUDSON-2ND ST) 100 SECOND ST HUDSON WI 54016-1504

Mat/Oth/Sub Charges		Ext'd Price
R404A/HP62 REFRIGERANT Ib LEAK DETECTOR Truck Charge	QTY 2.00 @ \$30.1100 QTY 1.00 @ \$10.0000 QTY 1.00 @ \$45.0000	\$60.22 \$10.00 \$45.00
	Mat/Oth/Sub Subtotal	\$115.22
	SUBTOTAL SALES TAX 5.5000% INVOICE TOTAL	\$337.22 \$6.34 \$343.56
	1 PERCENT 10/NET 30	











Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

INVOICE

Michael Hejduk 3-26-2024 WI0005-9501 BM Cooler 60000

> Invoice No.: Invoice Date: Client:

128063 03/26/2024 **CAP007**

AUT011-000046 Site: 1of 2

Page: Service Location CROSS AMERICA (BALDWIN) 1040 BERGSLIEN ST

BALDWIN WI 54002-0532

Amount Due:

\$953.60

Work Order Id: 203996 Completion Date: 03/12/2024

ALLENTOWN PA 18101

P.O. #: Case# 00018284 Job Id: WESRS118267

Work Requested:

Beer cooler is broken - may need replacement. NTE 1500.00

Equipment: 2 Door Cooler

CROSS AMERICA PARTNERS Email Invoices: cap_ap@caplp.com 645 HAMILTON STREET, STE. 400

> Model Serial #:

MC1300H-1-B 3207X99299

Work Performed:

Mar 12, 2024 - jcroel

Arrive on site, unit not running. Check site history and do not see anything for condensation. Plug unit in, pops breaker. Pulled out condensing unit from base and tried again, unit ran until trying to place back where it goes. Pops breaker again. Checked compressor with analyser, good. Checked wiring, temp sensor not passing voltage, need new one. Bringing old one to shop for mike g.

Mar 12, 2024 - jcroel

Replaced temp control. Unit running high head high suction, high compressor amps. Pulled charge, severly overcharged. Weighed in new charge. Unit pulling down to temp. 4 superheat, off at 33 case temp on at 37

Labor Charges						Ext'd Price
Technician Regular	03/12/2024	HRS.	6.25	@	\$111.0000	\$693.75
Mat/Oth/Sub Charges						Ext'd Price
R134 REFRIGERANT Ib THERMOSTAT CUT-IN 37F 84IN CAP Truck Charge		QTY QTY QTY	1.00 1.00 1.00	0	\$23.3300 \$134.8100 \$52.0000	\$23.33 \$134.81 \$52.00
		Mat/Ot	th/Sub S	ubtot	al	\$210.14





INVOICE



Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

> CROSS AMERICA PARTNERS Email Invoices: cap_ap@caplp.com 645 HAMILTON STREET, STE. 400 ALLENTOWN PA 18101

Invoice No.: Invoice Date: 128063 03/26/2024

Client: Site:

CAP007 AUT011-000046

Page: 2of 2

Service Location CROSS AMERICA (BALDWIN) 1040 BERGSLIEN ST BALDWIN WI 54002-0532

SUBTOTAL SALES TAX 5.5000% INVOICE TOTAL \$903.89 \$49.71 **\$953.60**

1 PERCENT 10/NET 30









Benedict Refrigeration Service, Inc. 1003 Harlem St. · Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

INVOICE

Michael Hejduk 3-20-2024 MN0018-5505 BM Coolers 60000

> Invoice No.: Invoice Date: Client:

127840 03/19/2024 **CAP007**

Site: AUT011-100018 Page: 1of 1

Service Location BP #MN0018 (WINONA) MN0018 920 MANKATO AVENUE WINONA MN 55987

Amount Due:

P.O. #: 00019215

Job Id: WNSRS118279

\$315.46

Work Order Id: 204108 Completion Date: 03/18/2024

ALLENTOWN PA 18101

Work Requested: 5 DOOR FREEZER WARM NTE \$2,000

CROSS AMERICA PARTNERS Email Invoices: cap_ap@caplp.com 645 HAMILTON STREET, STE. 400

Equipment: 5 door reach in freezer

RI-5-DFR-63 Model E9374204 Serial #:

Work Performed:

Mar 14, 2024 - cwhite
The unit was not running on arrival. Checked breaker and power to case. Found condensing unit on roof. Nothing was labeled had to figure out which condenser was for the five-door region freezer. There was power to the unit. Compressor was not starting. Checked pressure. Found unit had no refrigerant in it. Due to the age and visual condition of the unit and cost of possible repairs, I recommended getting quoted for a new system. Customer agreed and said to submit a quote.

Labor Charges						Ext'd Price
SCHOMBURG MN Technician Regular SCHOMBURG Technician No Bill	03/14/2024 03/14/2024	HRS. HRS.	2.75 0.50	@	\$103.0000 \$0.0000	\$283,25 \$0.00
		Labor	Subtota	al		\$283.25
Mat/Oth/Sub Charges						Ext'd Price
Truck Charge		QTY	1.00	@	\$30.0000	\$30.00
		SALE	OTAL S TAX ICE TO		.3750%	\$313.25 \$2.21 \$315.46
		1 PEI	CENT	10/NE	T 30	









Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

INVOICE

Michael Hejduk 4-12-2024 MN0018-5505 C-Store 60038

> 126939 Involce No.: Invoice Date: 02/28/2024 **CAP007** Client:

Site: AUT011-100018

Page: 1 of 3

CROSS AMERICA PARTNERS Email Invoices: cap_ap@caplp.com 645 HAMILTON STREET, STE. 400 **ALLENTOWN PA 18101**

203081

Service Location BP #MN0018 (WINONA) MN0018 920 MANKATO AVENUE WINONA MN 55987

> **Amount Due:** \$854.85

P.O. #:

Job Id: WNSRS118279

Completion Date: 02/21/2024

Work Order Id:

Work Requested: 3 issues

1)Freezer

2)Open air cooler 3) Ice machine

Equipment: pop ice machine

Model N0422A-1A 12091320013021 Serial #:

Work Performed:

Feb 14, 2024 - tfrey

Arrived on site. Started with soda fountain ice machine. Found water lines were removed from ice machine. Installed a water line with existing materials left on site. After getting water to machine turned on machine. Found water over flowing out of sump on I/m. Checked sump and noticed that float was bent so water would not stop. Bent float switch so it would stop water before over flow. While I was working on sump, Water sensor had a broken wire. Replaced female spade terminal and cleaned sensing prongs.

Started unit, leaking has stopped and water sensor is working. I/m started to make ice. After I got i/m to work shut it down for a cleaning. Ran ice machine throw a chemical clean and sanitized. Rinsed out bin that had debris and sanitized.

After cleaning, Started to make ice and let run. After 3 hours we shut off ice machine. I spoke with Stephanie on site and let her know ice machine is operating properly. She would like a quote on a new ice machine that is a cuber for right side soda machine. I will start the paper work.

Equipment: ice machine in back

Model CME506AS-1F Serial #: 04071320014833

Work Performed:

Feb 14, 2024 - tfrey

Onsite to check ice machine. Started ice machine to make ice. After running I/m for 15 minutes no ice had formed on evaporator. Compressor is running but no pressure difference. Ice machine has a bad compressor. I spoke with Stephanie and she would like it completely unhooked and shut down. Ice Machine in back will not be replaced by anything.

Ice machine checked out, customer does not want any parts installed.









Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

Invoice No .: Invoice Date:

126939 02/28/2024 CAP007

Client: Site: Page:

AUT011-100018 2of 3

CROSS AMERICA PARTNERS Email Invoices: cap ap@capip.com 645 HAMILTON STREET, STE. 400 ALLENTOWN PA 18101 Service Location BP #MN0018 (WINONA) MN0018 920 MANKATO AVENUE WINONA MN 55987

Equipment: open case cooler

Model Serial #:

ECSS60R 13081377834-2

Work Performed: Feb 14, 2024 - tfrey

On site to check out open display. Customer stated it has not worked since they gotten store. Started unit in store and went to find condenser. Found condenser on roof. Powered up condenser and checked pressures, coils, fans, and contactors. Condenser is in good shape and charge is full. Returned back down stairs to check case. Case is cooling properly. Ran unit through a defrost and unit defrosted properly. After defrost let unit cool again and unit pulled down fast. Blew out bottom of display with CO2 to clean out dust so does not clog any coils. Replaced all covers and let Stephanie know it is operating properly.

Equipment: W/l cooler evap

LSC200HS1 Model Serial #: D93E01544

Work Performed: Feb 14, 2024 - tfrey

On site to inspect walk in cooler. Powered on walking cooler and let run. Went to roof and checked Coils, fans ,contactors and refrigerant. Condenser checked out good and refrigerant is full . Checked evaporator and coils are clean , thermostats are operating properly. door heaters are working. There is one fan that will need to be replaced on left evaporator. I talked with Stephanie and she would like a quote first.

Powered down walk in cooler after it was checked out.

2.21.24 SIM SUBMITTED QUOTE TO DALLAS. COMPLETING THIS WORK ORDER ~pKS

					Ext'd Price
02/14/2024	HRS.	7.50	@	\$103.0000	\$772.50
					Ext'd Price
	QTY	2.00	@	\$0.8000 \$5.7400	\$1.60 \$11.48
	QTY	6.00	@	\$2.3300	\$13.97 \$4.65
	QTY	1.00 1.00	000	\$15.0000 \$30.0000	\$15.00 \$30.00
		QTY QTY QTY QTY QTY QTY	QTY 2.00 QTY 2.00 QTY 6.00 QTY 2.00 QTY 1.00	QTY 2.00 @ QTY 2.00 @ QTY 6.00 @ QTY 2.00 @ QTY 2.00 @ QTY 1.00 @	QTY 2.00 @ \$0.8000 QTY 2.00 @ \$5.7400 QTY 6.00 @ \$2.3300 QTY 2.00 @ \$2.3300 QTY 1.00 @ \$15.0000





INVOICE



Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

> **CROSS AMERICA PARTNERS** Email Invoices: cap ap@caplp.com 645 HAMILTON STREET, STE. 400 ALLENTOWN PA 18101

126939 Invoice No.: 02/28/2024 CAP007 AUT011-100018 Invoice Date: Client:

Site: Page: 3of 3

Service Location BP #MN0018 (WINONA) MN0018 920 MANKATO AVENUE WINONA MN 55987

Mat/Oth/Sub Subtotal \$76.70

SUBTOTAL SALES TAX INVOICE TOTAL \$849.20 \$5.65 **\$854.85** 7.3750%

1 PERCENT 10/NET 30







ENEDIC Sales & Service **SINCE 1938**

Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

INVOICE

Michael Hejduk 4-12-2024 MN0018-5505 BM Cooler 60000

> Invoice No.: Invoice Date: Client:

126933 02/28/2024 CAP007

AUT011-100018 Site: Page: 1of 2

Service Location BP #MN0018 (WINONA) MN0018 920 MANKATO AVENUE WINONA MN 55987

CROSS AMERICA PARTNERS Email Invoices: cap ap@caplp.com 645 HAMILTON STREET, STE. 400 ALLENTOWN PA 18101

Amount Due:

\$397.45

Work Order Id: 203164 Completion Date: 02/23/2024 P.O. #:

Job Id: WNSRS118279

Work Requested:

ORDER AND INSTALL EVAP FAN MOTOR IN WALK IN

Equipment: W/I cooler evap

Model Serial #:

LSC200HS1 D93E01544

Work Performed:
Feb 23, 2024 - tfrey
I arrived onsite and took off the guard and fan. Then I took out the fan motor and installed the new one. After that I turned the power on and the motor wasn't running properly. I thought the motor was bad so then I ran to the Winona shop to grab a new motor. Then when I got back to the site I checked for voltage and wasn't getting what it should be. So then I checked over wiring and saw that there was a split in the wires. After I fixed that I put the new motor and tested the motor. Fan motor running properly.

Labor Charges						Ext'd Price
SCHOMBURG Technician No Bill WN MN TECHNICIAN REGULAR	02/23/2024 02/23/2024	HRS. HRS.	0.50 2,75	@	\$0.0000 \$103.0000	\$0.00 \$283.25
		Labor	Subtota	d		\$283.25
Mat/Oth/Sub Charges						Ext'd Price
ORANGE/BLUE WIRE NUT O/B+ EVAP FAN MOTOR FREIGHT		QTY QTY QTY	2.00 1.00 1.00	@	\$0.3800 \$93.0600 \$12.5400	\$0.76 \$93.06 \$12.54
		Mat/Of	h/Sub S	ubtot	al	\$106.36





INVOICE



Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

> CROSS AMERICA PARTNERS Email Invoices: cap ap@caplp.com 645 HAMILTON STREET, STE. 400 ALLENTOWN PA 18101

Invoice No.: Invoice Date:

126933 02/28/2024 CAP007

Client: Site:

AUT011-100018 2of 2

Page:

Service Location BP #MN0018 (WINONA) MN0018 920 MANKATO AVENUE WINONA MN 55987

SUBTOTAL SALES TAX INVOICE TOTAL 7.3750% \$389.61 \$7.84 **\$397.45**

1 PERCENT 10/NET 30









INVOICE

Formerly known as:



Invoice No.: Invoice Date:

92437 01/11/2022

Client: Site:

AUT011 AUT011-100018

Page: 1 of 1

CROSSAMERICA PARTNERS 600 HAMILTON ST. SUITE 500 **ALLENTOWN PA 18101**

Service Location ERICKSON'S OIL PRODUCT #MN0018 (WINONA) MN0 920 MANKATO AVENUE WINONA MN 55987

Work Order Id: 173572

ENEDICT

Sales & Service **SINCE 1938**

Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720

715.834.3191 • 800.944.3604

www.BenedictSS.com

P.O. #: Job Id: WNSRS113684

Completion Date: 01/07/2022

Work Requested: W/I COOLER WARM, AT 50 DEGREES

Equipment: WALK-IN COOLER CONDENSER

Model NOT READABLE Serial #: Not Readable

Work Performed:
Jan 7, 2022 - jstanis
Found condensing unit locked out on low pressure. Leak checked around condensing unit and evaporators and didn't pickup any trace's of refrigerant with the leak detector. Started condensing unit and charged to a clear sight glass. We were on this system in the summer when they first started up the facility leak checking and cleared the sight glass then. Thinking the system was only charged to a clear sight glass then and now with the extreme cold the system was holding back causing the low charge. Cooler was running and at 35 degrees when I left.

Labor Charges						Ext'd Price
WN MN TECHNICIAN REGULAR	01/07/2022	HRS.	1.75	@	\$97.0000	\$169.75
Mat/Oth/Sub Charges						Ext'd Price
MO99 / R438A REFRIGERANT LEAK DETECTOR Truck Charge	2	QTY QTY QTY	4.00 1.00 1.00	@	\$25.3300 \$10.0000 \$15.0000	\$101.32 \$10.00 \$15.00
3-3			th/Sub S	ubtota	al	\$126.32
W N 001	8	INVO	ICE TOT		30	\$296.07
WNOO	bolers 600)(







L&D Maintenance, Inc.

13877 17th St. North Stillwater, Minnesota 55082 651-303-4747 Phone:

Fax: 651-337-1118

Michael Hejduk 4-9-2024 WI0005-9501 BM Other 60000

Invoice

DATE	INVOICE #
4/8/2024	2024-2059

BILL TO	SHIP TO
Cross America	W10005-9501 Baldwin Wi

P.O. NUMBER	TERMS	REP	SHIP	VIA	F.O.B.	PF	ROJECT
00018275			4/8/2024				
QUANTITY	ITEM CODE		DESCRIPT	TON	PRICE I	EACH	AMOUNT
	L & M truck charge	walls (FRP) reg	door lock and replated so they would be labor at 625,00 T	ice with new . Patch	Total	928.26	928.26 75.00
					Payments	creats	\$0.00
					Balanc	e Due	\$1.003.26



 Reference No.:
 0131818

 Date:
 14-Mar-2024

 Due Date:
 14-Mar-2024

 Customer ID:
 COD-ONLY

 Currency:
 USD

BILL TO:

MARATHON 1040 BERGSLIEN ST BALDWIN WI 54002-2501 United States of America Attn: MANAGER SHIP TO:

MARATHON - 1 1040 BERGSLIEN ST BALDWIN WI 54002-2501 United States of America Attn: MANAGER

	OMER REF. NUMBER 00017758	EXTERNAL REF NUMBER	CONTACT		
NO.	ITEM	S/N	QTY. UOM	UNIT PRICE	EXTENDED PRICE
1	LBR-T2SVC-HOURLY: T1 Hourly NOTE: 2843965 - [TT1]	- Labor - Tier 2 Service -	1.25 HOUR	119.0000	148.75
2	FUEL SURCHARGE: Fuel	Surcharge	1.00 CHG	10,0000	10.00
3	TRVL-T2-HOURLY: T1 - T NOTE: 2843965 - [TT1]	ravel - Tier 2 - Hourly	2.00 HOUR	119.0000	238.00
4	K0001285: 1/4 SPLICER (S	S/S)	1.00 EA	0.6630	0.66
5	K0001497: 12,3 OETIKER AlternateID: 16208		4.00 EA	0.2380	0,95

NOTE:

CAPUCCINO WATER LINES SPRUNG A LEAK TO THE POINT OF FLOODING NEED REPAIR

COD PRE AUTH# PA030424-02 FOR \$220.0
2024-03-14
Found backflow, preventer leaking
Cut out backflow, preventer, and spliced tube with splicer and OETIK ER
Tested for leaks working properly at this time
Equipment Serviced:
Model: GEMTIF1081000 Serial: 13792758

Signed By: SHELLY Service Call Date: 03-14-2024

> Please remit payments to: Pentair Commercial Services, LLC P.O. Box 7410471 Chicago, IL 60674-0471 630-904-1555

 Sales Total:
 398.36

 Tax Total:
 21.91

 Total (USD):
 420.27



Michael Hejduk 4-11-2024

Invoice

Remit To:

40588

PO Box 1053

Lexington, KY

M&M Service, Inc.

WI0054-9503 **Please Note New Remit To**

FM Dispensers 60020

Invoice Number: 0144518-IN 4/3/2024

Invoice Date:

Order Number: \$700154 Order Date: 3/28/2024 Salesperson: MM28

Customer Number: 02-521378

www.mid-valleysupply.com 106 Commerce Drive., South Point, OH 45680

315 East 15th Street, Covington KY 41011 2228 Yandes Street, Indianapolis, IN 46205 4080 N. 20th Ave, Wausau, WI 54401

Sold To:

859.781.0402

859.781.1451 fax

CrossAmerica Partners, LP 645 Hamilton Street, Suite 400 Allentown, PA 18101 Confirm To:

Ship To:

Holiday Neillsville SSG 1 Hewett St Neillsville, WI 54456



Page:

Customer P.O. 00020995		Ship VIA	F.O.B.		Terms Net 15		
Item Code	Descrip	tion		Ordered	Shipped	Price	Amount
/XSERVICE		uts down, reboots s down & reboots periodica	ally. Site has rebooted	1,000 I the commander.	1.000	0.0000	0.00
		B, Tech arrived onsite. Rel settings for one touch appr					
310-0103	BATTER	RY PACK RUBY CI		1.000	1.000	62,0000	62.00
/SERVICE FEE	- WI Service	Fee		1.000	1,000	35,0000	35.00
/STD-STRD-WI		d-Standard Wisconsin La ours: 1,50		1.500	1.500	106,0000	159,00
/TRIP CHARGE	-WI Trip Cha	arge 03/29/24		1,000	1,000	206,2500	206,25

Net Invoice:	462,25
Less Discount:	0.00
Freight:	0.00
Sales Tax:	25.43
Invoice Total:	487 68



Reference No.: Date: Due Date: Customer ID: Currency: 0131755 14-Mar-2024 14-Mar-2024 COD-ONLY USD

BILL TO: HOLIDAY 100 SECOND ST

HUDSON WI 54016-1504 United States of America Attn: MANAGER SHIP TO:

HOLIDAY 100 SECOND ST HUDSON WI 54016-1504 United States of America Attn: MANAGER W18062

CONTACT EXTERNAL REF NUMBER CUSTOMER REF. NUMBER WO#: 00017603 QTY. UOM UNIT PRICE EXTENDED PRICE NO. ITEM S/N 238.00 119.0000 LBR-T2SVC-HOURLY: T1 - Labor - Tier 2 Service -2.00 HOUR Hourly NOTE: 2843962 - [TT1] 10.0000 10,00 1.00 CHG 2 FUEL SURCHARGE: Fuel Surcharge 3.00 HOUR 119.0000 357.00 TRVL-T2-HOURLY: T1 - Travel - Tier 2 - Hourly 3 NOTE: 2843962 - [TT1] 18.97 1.00 EA 18.9720 K0002990: Wilbur Curtis WC-37118 Kit, Whipper Plate

AlternateID: WC-37118

NOTE:

COFFEE BREWER AND THE CAPPUCCINO MACHINE THE CAPPUCCINO MACHINE IS LEAKING EVERY TIME SOME ONE USES IT COFFEE BREWER ONE SIDE DOESNT WORK PROPERLY

COD PRE AUTH# PA030424-01 FOR \$220,0

2024-03-13

Coffee brewer is working properly at this time no issues found

Opened up cappuccino machine

Found plate to be leaking

Disassembled, whippers chamber removed, paddle and replaced whipper plate

Reassembled, mixing chamber and tested for proper operation cappuccino machine working properly at this time

Equipment Serviced:

Model: SCPC3D1002 Serial: 1-000-9855

Signed By: SHAYLA

Service Call Date: 03-13-2024

Please remit payments to: Pentair Commercial Services, LLC P.O. Box 7410471 Chicago, IL 60674-0471 630-904-1555
 Sales Total:
 623.97

 Tax Total:
 34.32

 Total (USD):
 658.29





Invoice			
Date	Invoice #		
4/10/2024	0000141200		

Bill To

CrossAmerica Partners (CAP) 645 Hamilton Street, Suite 400 Allentown, PA 18101-2192

OL:		T-
Shi	ρ.	10

MN0045 - Hermantown 4221 Haines Road Hermantown, MN 55811

	Payment Terms	Due D	ate	Rep	Ship Date	
00022589	Net 30	5/10/20	024	DTHSV	4/10/2024	
Description			Qty	Rate	Amount	
#9. Ethernet port went out. Travel Time Labor Mobilization Fuel/Vehicle Maintenance Su	1 tested good. Replaced ix book urcharge d sn# IXJ065407 new ix IXJD		0.25 1 1 1	96.00 96.00 45.00 15.00 1,150.00	96.00 24.00 45.007 15.007	
			Subtotal		\$1,330.00	
You may make payments via cas https://swipesimple.com/links/lnl	h, check OR pay with Credit Card	d at:	Subtotal Sales Tax	(8.875%)	\$1,330.00 \$107.39	
You may make payments via cas https://swipesimple.com/links/lnl A Non-Cash Charge of 3.5% wil	h, check OR pay with Credit Card 4d974f74 I be added to your total due.	d at:	COLUMN TO SERVICE STATE OF THE	(8.875%)	2.3.2.1.3	
Invoice is valid unless inquiries a You may make payments via cas https://swipesimple.com/links/lnl A Non-Cash Charge of 3.5% wil Let us know if you want to go to Email to: salesbilling@mnpetro. Please include your company nar	h, check OR pay with Credit Card c_4d974f74 I be added to your total due. paperless. com	d at:	Sales Tax		\$107.39	



GALAXY FMS 201 S Blakely Street, Suite 251 Dunmore, PA 18512

Phone # 888-689-3487 Fax # 888-689-3492

https://galaxyfms.com/

-Invoice # 210514

Invoice Date 3/1/2024

Due Date 3/11/2024 Our W/O # 114490

Order Type General

Category Construction

PO # IYS-MSO-LC-MN0039

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

SERVICE LOCATION

Joe's Kwik Mart - Loc # MN0039 5995 Hodgson Rd Shoreview, MN 55126 Phone #

JOB DESCRIPTION

- -Furnished and installed broken window.
- -Furnished and installed 1 2x4 fixture in back room, new lamps, and ballast.
- -Furnished and installed 48 T8 4100K Lamps on the main sales floor.
- -Furnished and installed 4 lenses on main salesfloor that are broken.
- -Furnished and installed 2 walk in cooler lights that are not working.
- -Furnished and installed 5 soffit lights that are not working with new lamps and ballast as needed.

LABOR and MATERIALS

Qty Description Man Hour Unit Price Total Tax 1 Labor and Material 16,909.00 16,909.00

LAS COUNTY CON EX

NET 10 Subtotal 16,909.00 Please Remit Payment To: Tax 0 % 0:00 Galaxy Group, LLC Total 6,909.00 471 N Broadway Suite 215 Balance 6,909.00 Jericho, NY 11753

Print Date: 03/01/2024

Net 10 Days

Page 1 of 1



GALAXY FMS 201 S Blakely Street, Suite 251 Dunmore, PA 18512

Phone # 888-689-3487 Fax # 888-689-3492

https://galaxyfms.com/

SERVICE LOCATION Joe's Kwik Mart - Loc #\MNOD2 1709 2nd Ave W

International Falls, MN 56649

Invoice # 210516 Invoice Date 3/1/2024 Due Date 3/11/2024

Our W/O # 114574

Order Type General

Category Construction

PO # IYS-MSO-LC-MN0026

Phone #

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

JOB DESCRIPTION

Inside Work:

Furnished and installed 10-6 T12 Single Pin Lamps for Cooler Doors

Outside Work:

Furnished and installed 6 wall pack light fixtures on exterior of location.

Furnished all labor and materials to repair two 2) Parking Lot Light with New LED Direct Drive Lamp.

Furnished and installed one (1) Cree Gas Canopy Light.

LABOR and MATERIALS

Qty Description

Labor & Material

Man Hour

Unit Price

Total Tax

18,636.36

18,636.36

NET 10

Please Remit Payment To:

Galaxy Group, LLC 471 N Broadway Suite 215 Jericho, NY 11753

Subtotal Tax 0 %

Total

Balance

18,636.36 0.00 18,636.36 18,636.36



Galaxy Group

GALAXY FMS
201 S Blakely Street, Suite 251
Dunmore, PA 18512
Phone # 888-689-3487 Fax # 888-689-3492
https://galaxyfms.com/

Invoice # 210532

Invoice Date 3/4/2024 Due Date 3/14/2024 Our W/O # 114573

Order Type General
Category Construction

PO # IYS-MSO-LC-MN0025

145-Growth Coppy

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101 SERVICE LOCATION

Joe's Kwik Mart - Loc # MN0025 301 4th St International Falls, MN 56649 Phone #

JOB DESCRIPTION

Inside Work:

Furnished and installed 30-4 T-8 Lamps and Ballasts on Sales Floor.

Furnished and installed 2-2 T-8 Lamps and Ballasts.

Furnished and installed 26-8 T12 Lamps in BOH

Furnished and installed 26-8 T12 HO Lamps for Cooler Doors

Furnished and installed 8-6 T12 Single Pin Lamps for Cooler Doors

Furnished and installed 2 Bath fans in restrooms.

Furnished and installed New Track Light on Sales Floor.

Furnished and installed New Faucet in Men's restroom.

Furnished and installed New Toilet in Men's restroom.

Furnished and installed replace glass in 1 broken window.

Furnished and installed New Glass in windowpane.

Outside Work:

Furnished all labor and materials to trouble shoot Road Sign - Replace LED Diesel Driver. Furnished all labor and materials to replace 9 soffit lights with LED Direct Wire Lamps

Furnished and installed 1 wall pack light fixtures on exterior of location.

Furnished all labor and materials to repair one (1) Parking Lot Light with New LED Direct Drive Lamp.

LABOR and MATERIALS

Qty Description Man Hour Unit Price Total Tax

Labor & Material 54,045.23 54,045.23

 NET 10
 Subtotal
 54,045.23

 Please Remit Payment To:
 Tax 0 %
 0.00

 Galaxy Group, LLC
 Total
 54,045.23

 471 N Broadway
 Balance
 54,045.23

 Suite 215
 Jericho, NY 11753
 54,045.23

Print Date: 03/04/2024 Net 10 Days Page 1 of 1



Minnesota Petroleum Service, Inc. 682 39th Ave NE Columbia Heights, MN 55421 763-780-5191 www.mnpetro.com



Inv	Invoice			
Date	Invoice #			
4/10/2024	0000141220			

Bill To

CrossAmerica Partners (CAP) 645 Hamilton Street, Suite 400 Allentown, PA 18101-2192

Chin	Ta
Ship	10

MN0018 - Winona 920 Mankato Ave Winona, MN 55987

PO#	Payment Terms	Due D	ate	Rep	Ship Date
00022445	Net 30	5/10/2	024	SERV	4/10/2024
Description			Qty	Rate	Amount
Labor - RM 4-9-24: P-6 stuck board, found keypad came up rewiped/loaded jade board- To P-12 bagged by Tanknology f Compliance Division will be a Emergency Response charge Mobilization Travel Time Labor Fuel/Vehicle Maintenance Su SPM SHA2 Wayne Generic New sn A1233170096 Old sn A1170120300 Remote Key Injection	breached- R&R keypad, est ok. P-5 working/inservice. for a south 87 tank line issue there on Thursday to address.	P-7 thru		75.00 5 45.00 96.00	75.00 225.007 480.00 75.007 984.447
Invoice is valid unless inquiries a		4	Subtota	ı	\$2,119.43
https://swipesimple.com/links/lnl	You may make payments via cash, check OR pay with Credit Card at: https://swipesimple.com/links/lnk_4d974f74 A Non-Cash Charge of 3.5% will be added to your total due.			ax (7.375%)	\$97.67
Let us know if you want to go to paperless.			Total		\$2,217.10
Email to : salesbilling@mnpetro Please include your company na	.com		Paymer	ts/Credits	\$0.00
A finance charge of 1.5% Monthly (18% Annually) will be assessed on balances 30 days and over.		Balan	ce Due	\$2,217.10	



GALAXY FMS 201 S Blakely Street, Suite 251 Dunmore, PA 18512 Phone # 888-689-3487 Fax # 888-689-3492

https://galaxyfms.com/

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

Invoice # 210515

Invoice Date 3/1/2024 Due Date 3/11/2024 Our W/O # 114491 Order Type General

Category Construction

PO # IYS-MSO-LC-MI0002

SERVICE LOCATION

Joe's Kwik Mart - Loc # MI0002 405 N Stephenson Ave Iron Mountain, MI 49801 Phone #

JOB DESCRIPTION

Furnished and installed six new cooler façade lights to replace non-working fixtures. Furnished and installed fixtures in the office.

Furnished and installed four fixtures in the can room and ice maker rooms.

Furnished and installed one existing non-working 8-foot strip light in the retail area.

Furnished and installed one new 8' strip light in the walk-in cooler.

Furnished and installed one wall pack on each end of the building.

Cleaned and retrofitted the five (5) existing store canopy lights with LED corn cob lights.

Furnished and installed Retrofit the nine-door cooler with LED tubes.

Furnished and installed Stained Ceiling tiles were required.

Adjusted two Entrance doors.

Furnished and installed two sweepers on the main entrance doors.

Repaired Brickwork near main entrance doors.

Recharged Condenser for a walk-in cooler.

IADAD		MATERIALS
LADUK	ana	MATERIALC
		THUTTHES

	N and MATERIALS			
Qty	Description	Mea Head	C702.2011	
1	Labor & Material	Man Hour	Unit Price	Total Tax
	2 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 -		25,163,22	25,163.22

Micay Micay

NET 10	C. M. M.	
Please Remit Payment To:	Subtotal	25,163.22
Galaxy Group 11 C	Tax 0 %	0.00
471 N Broadway Suite 215	Total	25,163.22
Jericho, NY 11753	Balance	25,163.22

Michael Hejduk

859.781.0402 859.781.1451 fax

www.mid-valleysupply.com

106 Commerce Drive., South Point, OH 45680 315 East 15th Street, Covington KY 41011 2228 Yandes Street, Indianapolis, IN 46205 4080 N. 20th Ave, Wausau, WI 54401

Remit To:

M&M Service, Inc. PO Box 1053 Lexington, KY 40588

Invoice Number: 0144517-IN

Invoice Date: 4/3/2024

Order Number: \$700153 Order Date: 3/28/2024 Salesperson: MM28 **Customer Number:** 02-521378

Sold To:

CrossAmerica Partners, LP 645 Hamilton Street, Suite 400 Allentown, PA 18101 Confirm To:

Ship To:

CAPL Retail LLC DBA JKM MI0002 405 N. Stephenson Avenue Iron Mountain, MI 49801

O0020855	7	Ship VIA	F.O.B.		erms et 15		
Item Code		Description		Ordered	Shipped	Price	Amount
/XSERVICE	PROBLEM: F	Fp2 & 3 nozzles, fp5 CC reader 3 handle broken, Fp 2 nozzle leaking, F	p 5 card reader i	1.000 not working.	1.000	0.0000	0.00
	SOLUTION: 3/ nozzle on pum	29/24, TA, Tech arrived onsite. Replace on pump #2. Ve	ed a bad card read erified operations	der on pump #5, a c and all tested OK.	damaged		
W2893895-002		SVC KIT CARD READER SECURE CI	HI	1.000	1.000	1,414.5330	1,414.53
241TPS-0241		SWVL VALUE HOSE 3/4"		1.000	1.000	51.0870	51.09
11BP-0400		NOZZLE GAS BLK 3/4"" NPT NEW		2.000	2.000	136.9400	273,88
SERVICE FEE	- MI	Service Fee		1.000	1.000	35.0000	35.00
/STD-STRD-MI	03/29/24 Tony	Standard-STD Michigan Labor A Hours: 2.75		2.750	2.750	106.0000	291.50
TRIP CHARGE	-MI	Trip Charge 03/29/24		1.000	1.000	212.2500	212.25

Net Invoice:	2,278.25
Less Discount:	0.00
Freight:	0.00
Sales Tax:	106.47
Invoice Total:	2,384.72



Invoice

Billing Address

Lorie Conde| Accounting Associate Cross America Partners LP 645 Hamilton St Ste 400 Allentown PA 18101-2130 United States

For Work At

Marathon Gas #WI0062 100 2nd St Hudson WI 54016-1504 United States

Invoice Date	Invoice #	Web Pmt Pin	Due Date	P0 #	Created From	Customer ID	Sales Rep
04/05/2024	INY-049829	8 11230189	06/04/2024	SA-6534 / Y73786	933000	243298:157	040470 Timothy J Holt
Quantity	Units	Item			Options	Rate	Amount
3	EA	LABOR 0' - 48' Standa Diagnose and repair t the south side causing incomplete.	he outages in the	fuel price sign on		\$105.00	\$315,00
5	EA	LABOR 0' - 48' Standa Service Labor	rd Reach Service	Labor		\$105.00	\$525.00
9	EA	Service Part Parts needed: to repai	r LED sign			\$2,234.38	\$2,234.38
						Subtotal	\$3,074.38
						Tax Total (%)	\$169.10
						Adjustment	
						Amount Paid	\$0.00
						Amount Due	\$3,243.48

Online Payment

Click the buttom below if you want to pay online with credit card or eCheck. Or go to https://apps.yesco.com/YESCOPayments/ and enter your Payment PIN: 11230189

Pay Online

Payment Options

Authorized Signature

Bill To: Remit To: Lorie Conde| Accounting Associate Cross America Partners LP SEND CREDIT CARD AUTHORIZATIONS TO: nationalservicecredit@yesco.com MAIL CHECKS TO: 645 Hamilton St Ste 400 Allentown PA 18101-2130 YESCO LLC **United States** PO Box 11676 Tacoma WA 98411-6676 **United States** 702-944-4538 Account Number: 243298:157 Invoice Number: INY-0498298 Due Date: 06/04/2024 Amount Paid: \$ **Credit Card Information** Card Holder's Name NOTE: All Charges Over \$1,000.00 will be assessed a 2% surcharge. Credit Card # Card Type MC DI VS AM Exp. CCV Date Card Billing Address City Zip State **ACH Payment Information** By completing your ACH information below, you authorize YESCO to withdraw all payment(s) pursuant to the Agreement on the applicable due date (s) from Customer's depository account as described below. Written revocation of this authorization must be received by YESCO with at least 30 days prior notice. Name on Bank Account Name of Bank Checking Savings Bank Account Number **Routing Number** Bank City and State **Payment Authorization** E-mail Address for Receipt Phone

Date



Trip Record

Job Site Address

Job Name

PO Job Trip Number Number Number SA-6534 / 7721 1

PARTS here - Hudson - Marathon - Gas Pricer

Y73786

- Array Const.

100 2nd St, Hudson, WI 54016-1504

Date

03/28/2024

Time On Site 03:57 PM

Time Checked Out

03:58 PM

Work Performed for Trip 1

3 LABOR - 1 MAN SERVICE LADDER VAN UP TO 45'


• 1 Parts needed: to repair LED sign

5 RETURN LABOR - 1 MAN SERVICE LADDER VAN UP TO 45'

Customer Name

Crew Name

Cargo Ladder





Michael Hejduk 4-16-2024 MI0001-6500 BM Doors 60000

GALAXY FMS

201 S Blakely Street, Suite 251

Dunmore, PA 18512

Phone # 888-689-3487 Fax # 888-689-3492

https://galaxyfms.com/

Invoice Date 4/4/2024
Due Date 4/14/2024
Our W/O # 114599
Order Type Door
Category Locksmith
PO #

Invoice # 211252

BILL TO

CrossAmerica Partners LLC 645 Hamilton Street Suite 400 Allentown, PA 18101

SERVICE LOCATION

Joe's Kwik Mart - Loc # MI0001 501 W Washington St Marquette, MI 49855 Phone #

JOB DESCRIPTION


- Arrived on site and met with manager
- Supplied and installed 2 locks
- Made all necessary adjustments
- Cleaned work area

LABOR and MATERIA	ALS
-------------------	-----

Qty	Description	Man Hour	Unit Price	Total Tax
1	Labor	2.00	95,00	190.00
1	Material		185,00	185.00
1	Trip charge		75.00	75.00

	Subtotal	NET 10
0.00	Tax 0 %	Please Remit Payment To:
450.00	Total	
450.00	Balance	471 N Broadway Suite 215 Jericho, NY 11753
2.22.0	T. 12 W	Suite 215

Issue date Mar 12, 2024



We appreciate your business.

Customer Mike Hejduk mhejduk@caplp.com 330-518-6470 655 S. Fostoria Rd

Port Clinton, OH 43452

Invoice Details
PDF created March 12, 2024
\$1,025.00

Payment
Due March 12, 2024
\$1,025.00

Items	Quantity	Price	Amount
recharge unit with hotshot 2 with labor Recharge unit to get unit up and running. Plan is to change out refrigeration units.	(1)	\$1,025.00	\$1,025.00
Subtotal			\$1,025.00

Total Due \$1,025.00



GARNER G.C.C

Design Build Maintain

INVOICE# 28220

DATE: 07/14/2024

984 Dalewood Rd Lyndhurst Oh, 44124 Phone 330 814 7487 E-mail Mickeydeon33@gmail.com

TO Nolan Lockner

SITE: OH0088

SHIP CAP

TO

Nlockner@caplp.com

Customer ID Cove Base/Health code violation

SALESPERSON	JOB	SHIPPING METHOD	SHIPPING TERMS	SITE NUMBER	PAYMENT TERMS	DUE DATE
Mickey	Cove Base Health code violation	N/A	N/A	OH0088	NET 30	08/15/2024

QTY	SERVICE	DESCRIPTION	UNIT PRICE	DISCOUNT	LINE TOTAL
140 linear ft.	Removal	Removed all old cove base (off white) and adhesive. Removed dry wall located underneath cooler doors (compromised dry wall cove base would not adhere).			1750.00
156 linear ft.	Install	Install 156 linear ft. of 6in. black cove base (bathroom, back hallway through out store) Install drywall under cooler doors, prep, prime, and paint to match.			
15 linear ft.	Remove/Install	Remove failing cove base in kitchen area (4in off white) Install 4 in. off white cove base.			
	Materials	6 in. black cove base, 4 in. off white cove base, adhesive glue, dry wall, hardware, paint (to match)			752.00
	Travel	5.7			100.00
	Comments	Health code violation			
			TOTAL		

SUBTOTAL 2,602.00

SALES TAX 208.16

TOTAL 2810.62

GARNER G.C.C

Design Build Maintain

INVOICE# 28221

DATE: 07/14/2024

984 Dalewood Rd Lyndhurst Oh, 44124 Phone 330 814 7487 E-mail Mickeydeon33@gmail.com

TO Nolan Lockner

SITE: OHOO88

SHIP CAP

TO

Nlockner@caplp.com

Customer ID Ceramic tile/Health code violation

SALESPERSON	JOB	SHIPPING METHOD	SHIPPING TERMS	SITE NUMBER	PAYMENT TERMS	DUE DATE
Mickey	Ceramic tile Health code violation	N/A	N/A	OH0088	NET 30	08/15/2024

QTY	SERVICE	DESCRIPTION	UNIT PRICE	DISCOUNT	LINE TOTAL
82	Remove	Removed 82 8x8 ceramic tiles. Removed boding thin set. Level floor where tiles were removed for install.			3,200.00
Throughout store	Install	Install all tiles that were removed throughout store. Per health code violation. Grout to match to previous grout.			
Remove and install	Kitchen area	Remove and replace cracked and missing 6x6 non slip tiles. Install 3 steel plates 18x63 diamond plated, painted black where structural beam was compromised for tile install.			
1	Pluming	Replace one shut off valve, and supply line to 3 bay sink.			
1	Service Misc. repairs needed	Repaired threshold by back door. Repaired threshold front door.			
	Materials	24 in x 8 in ceramic tiles, 8x8 tiles, Diamond plated steel plates, dark grey grout, speed set, shut off valve, water supply line,			1,150.00
	Travel	8.2			150.00

 Comments	Pictures on file. Before and after pictures sent to Nolan Lockner			
		TOTAL DISCOUNT		
			SUBTOTAL	4,500.00
			SALES TAX	360.00
			TOTAL	4860.00

Advance HVAC, LLC 14837 Detroit Ave # 112 Lakewood OH 44107

PH: 216-319-4444

Ohio License # 49772

Michael Hejduk 7-17-2024 OH0077-294 C-Store WIC 60036

Invoice

DATE	INVOICE#
5/28/2024	219

JOB LOCATION
8200 Columbia Road Olmsted Falls

DUE DATE	P.O. NUMBER
6/2/2024	

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
11 = 101	Walk in cooler Replace warranty compressor			0,00
	Install one new evaporator Install new expansion valve with new power elements Install new filter dryer New evaporator has 1 year manufacturer warranty			4,156.00
				125.00
	Install new contactor Wash condenser with metal safe chemical and rinse with			85.00
	waTER Upon starting the system and checking the opperation, discovered the old evaporator expansion valve is weak adjusted valve. Valve is functioning better but not to manufacturer recomendation.			95.00
Thank you for	your business!	Subtotal 0% Tax		4,461.
	1	Total		4,461
				4,461.

GARNER G.C.C

Design Build Maintain

INVOICE# 28223

DATE: 07/14/2024

984 Dalewood Rd Lyndhurst Oh, 44124 Phone 330 814 7487 E-mail Mickeydeon33@gmail.com

TO Nolan Lockner

SITE: OH0077

SHIP CAP

TO Nlockner@caplp.com

Customer ID Roof/carwash/store building

SALESPERSON	JOB	SHIPPING METHOD	SHIPPING TERMS	SITE NUMBER	PAYMENT TERMS	DUE DATE
Mickey	Roof carwash/store building	N/A	N/A	OH0077	NET 30	08/15/2024

UNIT	SCOUNT LINE TOTAL
	1850.00
	2100.00
	250.00
	75.00
PR	SCOU

TOTAL DISCOUNT	SUBTOTAL	4275.00
	SALES TAX	342.00
		-



2285 Ward Ave I Simi Valley, CA 93065 800-323-8107 I 877-619-7053 Fax pqlighting.com I info@pqlighting.com MNU39 60007

INVOICE

648578

CUSTOMER NO 6106252469 IDT 1

SOLD TO

CROSS AMERICA PARTNERS (CAP) 600 HAMILTON ST SUITE 500 ALLENTOWN, PA 18101 SHIP TO

FREEDOM - SHOREVIEW 5995 HODGSON ROAD SHOREVIEW, MN 55126

INVOICE DATE	1 0	SHIP VIA	F.O.B.	Shipping Loc.	PAYMENT TERMS
05/13/24		TRUCK	MN	1	NET 30
A. A. P. P. C. C. C.	RDER NUMBER	ORDERE	D B 1	PERSON	OUR ORDER NUMBER
	18279		05/13/24 HEIDI HOHE	RTZ (SERVICE)	3330719
QTY Q' ORDERED SHIF	TY QTY	ITEM NUMBER	DESCRIPTION	UNIT	DISC % EXTENDED PRICE
1	1	BUCKETTRUCK	-HIBUCKET TRUCK HALF DAY	50.00	50.00
į	1	LBRPAULF	LABOR - (1.5HRS) TRY OPEN SIGNOPEN THREE SIDES, GET INTO SIGNONE OF DRIVERS FOR SIGN CONNECTED TO POWER NO POWER NO POWER THE OTHER SIGN, CLOSE SIGN ALSO ROAD CONSTRUCTION GOON VERY CLOSE TO SIGN AND ELECTRICAL BOXES NEED TO CONNACT, GAIL ON ISSUES	WER 3N,	
6	6	LBR-DYLANDU	NDELABOR	95.00	570.00
6	6	LBRWILLA	LABOR	95.00	570.00
1	1	EK4236S	PHOTO-CONTROL ELECTRONIC STEM/SWIVEL 120/277V	74.55	74.5
50	50	30-673	WIRENUT WIRE CONNECTOR/ORANGE - 10,000	0.25 BOX	12.5
1	1	125-0028	MISCELLANEOUS MATERIALS TO 4 X 4 GREEN TREATED LUMBER	OTAL- 18.40	18.4
-t	·j	125-0028	MISCELLANEOUS MATERIALS T 4 X 4 X 8 POST, FITTINGS, CONI WIRE, BOXES COVERS	OTAL- 85.0 DUIT,	0 85.0
1	1	FS	FUEL SURCHARGE	25.0	0 25.0

COMMENTS:			Subtotal	1,547.95
Thank you for putting your customer number on your remittance.	Taxable	1,497.95	Sales Tax	125.45
	Non-Taxable	50.00	Total	1,673.40

1,673.40



Benedict Refrigeration Service, Inc. 1003 Harlem St. - Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

> BIII To: CROSS AMERICA PARTNERS Email Invoices: cap ap@caplp.com 645 HAMILTON STREET, STE. 400 ALLENTOWN PA 18101

Page: 1 of 2 CONTR118529 129668

CLIENT ID: INVOICE #: INVOICE DATE:

CAP007 129668 05/06/2024 06/05/2024

DUE DATE:

BILLED THROUGH: 05/06/2024

Site Address: 1 HEWETT ST NEILLSVILLE WI 54456-2162

CROSS AMERICA (NEILLSVILLE) (T & M) DD

THANK YOU FOR YOUR BUSINESS!

JOB ID: CONTR118529 PO #: 22375

AMOUNT

FIXED FEE ITEMS

CONTRACT ONTRACT %
AMOUNT COMPLETE

AMOUNT REMAINING

TOTAL BILLED TO DATE

AMOUNT **PREVIOUSLY** BILLED

THIS BILLING

LABOR MATERIAL

100.00% \$2,275.00 \$869.00 100.00% \$2,275.00 \$869.00 \$2,275.00 \$869.00

100.00% \$3,144.00

\$3,144.00

\$3,144.00

Invoice Subtotal Sales Tax **Total Invoice**

\$3,144.00 \$172.92 \$3,316.92

W1 0054

PLEASE REMIT TO: BENEDICT REFRIGERATION SERVICE, INC. 1003 Harlem Street Altoona, WI 54720-2203

Total Invoice

\$3,316.92











Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

Page: 2 of 2 CONTR118529 129668

EXPLANATION OF CHARGES

LABOR

LABOR

-CUTOUT OLD PIPING

-RAN NEW LINES -INSTALLED NEW RISER -REPLACED FILTER DRYER

-PULLED VACUUM, CHARGED SYSTEM -VERIFIED PULL DOWN

MATERIAL

MATERIAL

Details Totaling:

\$2,275.00

Details Totaling:

\$869.00

PLEASE REMIT TO: BENEDICT REFRIGERATION SERVICE, INC. 1003 Harlem Street Altoona, WI 54720-2203

Total Invoice

\$3,316.92







W10005





Benedict Refrigeration Service, Inc. 1003 Harlem St. • Altoona WI 54720 715.834.3191 • 800.944.3604 www.BenedictSS.com

BIII To: CROSS AMERICA PARTNERS Email Invoices: cap ap@caplp.com 645 HAMILTON STREET, STE. 400 ALLENTOWN PA 18101

CAP007 133647 07/29/2024 CLIENT ID: CAP007 INVOICE #: 133647 INVOICE DATE: 07/29/2024 DUE DATE: 08/28/2024 BILLED THROUGH: 07/29/2024

Site Address: 1040 BERGSLIEN ST BALDWIN WI 54002-0532

W10005

AMOUNT

CROSS AMERICA (BALDWIN) (HVAC) AE

PAYMENT RECEIVED - THANK YOU! CREDIT CARD, 6/24/2024 (\$8,255.45) BALANCE DUE \$8,014.17

JOB ID: CONTR118741 PO #:

FIXED FEE ITEMS	CONTRACT AMOUNT COMP	% AMOUNT	TOTAL BILLED TO DATE	AMOUNT PREVIOUSLY BILLED	AMOUNT THIS BILLING
HVAC EQUIPMENT INSTALLATION LABOR AND MATERIALS	\$9,586.73 100.	00% 00% 00%	\$6,442.44 \$9,586.73 \$240.45		\$6,442.44 \$9,586.73 \$240.45
3% CREDIT CARD PROCESSING FEE	e46 260 62 100	00%	\$16,269.62		\$16,269.62

\$16,269,62

100.00%


15800 WI 0005 CAP EAT MAINT LAVAR

PLEASE REMIT TO: BENEDICT REFRIGERATION SERVICE, INC. 1003 Harlem Street Altoona, WI 54720-2203

\$16,269.62 **Total Invoice**

Remaining Balance Due: \$8,014.17





BALDWIN PAPLIENT

sma Ichi dese cappan

BENEDICT SALES AND SERVICE 1003 NASLEM STREET ALTOONA, WI 54720 [215] 034-3191

06/14/14

11:00:35

PHONE ORDER

*********5650 FIRTY Medical MANUAL

W

Appr Code: 039882 Transaction ID: 0012
Host Trans ID: 384176605059452 Host Trans ID: 38417660
Batch: 498
Invoke: ID
Response: APPROVAL 093692
Approved: Online
AVS Code:0
CVV2 Code:MATCH M

Total:

\$ 8,255.45

NO SIGNATURE REQUIRED

THANK YOU Customer Copy



Minnesota Petroleum Service, Inc. 682 39th Ave NE Columbia Heights, MN 55421 763-780-5191

www.mnpetro.com



Invoice				
Date	Invoice #			
8/2/2024	0000146412			

Bill To

CrossAmerica Partners (CAP) 645 Hamilton Street, Suite 400 Allentown, PA 18101-2192

S	h:	~	T_{α}	u
	MII	01	HE C)
-	ш	~		а

MN0018 - Winona 920 Mankato Ave Winona, MN 55987

PO#	Payment Terms	Due D	ate	Rep	Ship Date
Gus verbal	Net 30	9/1/20	24	TW	8/1/2024
D	escription		Qty	Rate	Amount
Description Repipe outside three dispensers to be fed off of North 87 tank and cap off piping from south 87 tank (2 piping techs) Fravel Time Labor (x2 round trip) Mobilization Fuel/Vehicle Maintenance Surcharge Misc pipe fittings per dispenser Parsons Electric to move sub relay wiring for new 87 positions Poured back concrete Travel Time Labor Mobilization Fuel/Vehicle Maintenance Surcharge Concrete per yard - summer MN0018 - FM - Piping Repair Approved - GN			1 1,536.00 10 96.00 10 45.00 10 15.00 3 325.00 1 1,768.00 8 106.00 10 106.00 10 45.00 10 15.00 2 495.00		1,536.00 960.00 450.007 150.007 975.007 1,768.00 848.00 1,060.00 450.00 150.00 990.00
Invoice is valid unless inquiries are made within 15 days. You may make payments via cash, check OR pay with Credit Card at: https://swipesimple.com/links/lnk_4d974f74		ard at:	Subtotal Sales Tax (7.375%)		\$9,337.00 \$116.16
A Non-Cash Charge of 3.5% will be added to your total due. Let us know if you want to go to paperless. Email to: salesbilling@mnpetro.com Please include your company name and email address. A finance charge of 1.5% Monthly (18% Annually) will be assessed on balances 30 days and over.			Total		\$9,453.16
			Paymen	ts/Credits	\$0.00
			Balan	ce Due	\$9,453.16

Invoice

Date	Invoice #		
6/28/2024	062524-4377		

Carlson Refrigeration Lakeshore 1ce

602 Ogden Ave Superior, WI 54880 715-395-5513

73.1		٠
1211		0
Bil	- 1	

CrossAmerica Partners CrossAmerica Partners LP Attn: Trade Payables 645 Hamilton Street San Antonio, TX 78269

-	A	MA.
S	ervice	Site

Joe's Kwik Mart. 202 8th Street S Virginia, MN 55792

P.O. No. SA-13281		Terms	Due Date	Rep	Service Date	Ship Via
		Net 10 Days	7/8/2024	KJS	6/28/2024	Our Truck
Item		Description		Qty	Rate	Amount
Materials Coil Chemical Labor MN Mileage	condenser fan motors		detergent washed the	1 1 5 1	128.84 22.38 130.00 50.00	128.84° 22.38° 650.00 50.00
As of January 1, 2023, we will be imposing a 3% surcharge on all credit card charges		Sales	s Tax (7.375%	5) \$14.8		
		Tota	1	\$866.0		

Invoice

Date	Invoice #
6/25/2024	061024-427

Carlson Refrigeration Lakeshore Tee 602 Ogden Ave

602 Ogden Ave Superior, WI 54880 715-395-5513

Bill	To	
DIII	10	ı

CrossAmerica Partners CrossAmerica Partners LP Attn: Trade Payables 645 Hamilton Street San Antonio, TX 78269

C	ervice	Cita
0	ervice	Site

Joe's Kwik Mart. 202 8th Street S Virginia, MN 55792

	P.O. No. Terms Due Date		Rep	Service Date	Ship Via	
SA-12178 Net 10 Da		Net 10 Days	7/5/2024	BAS	6/25/2024	Our Truck
Item	Item Description			Qty	Rate	Amount
Labor MN Mileage	condenser all the way to	en I arrived I found that the suction the evaporator coil was completely next day. After returning found that the cleaned off evaporator coil and of the coil and the cleaned off evaporator coil and the cleaned	the evaporator coil	5.5	130.00	715.00 50.00T
the second of the second of the second of	As of January 1, 2023, we will be imposing a 3% surcharge on all credit card		Sales	Tax (7.375%	\$3.69	
charges		Tota	1	\$768.69		

Ŷ				1	M	A	I&H FN	NTERPRISE	S _		
AKE					1	1	OF M	ARQUETTE, LLC	DA	E/s	111/24
DDEL#					1		243 Heidtman	Rd Skandia, M 49	9885 CU	ST.	111/61
ER AL#				0		(906)	362-3956 · ja	ndh_enterprises@y		JR.	
CHECKLIST	D	ESCRIPTION OF	WORK		JOB LOC:),‡	
☐ COMPRESSOR										100.5	
O SUCTION PSI HEAD PSI O VOLTS AMPS ELECTRICAL CONNECTIONS OIL LEVEL & CHECK FIN COND.	ijean I	Dest.	achine Luit	needs	BILL TO:	3.7	P. 17/4+		Pi	HONE #	
CONDENSER COIL	lats of	TLL	and }	he					A	CCT.#	
CLEAN CORS CHECKFIN COND.	leaning)	3.4.	not b	Cork					-	_	or Downsteen
U VOLTS AMPS D ELECTRICAL CONNECTIONS U FAM PULLEYS (ADJUST BELT) D CHECK, LUBE BEARINGS & MOTOR	100%.	nay	110			F	Lugal		V	VORK OF	DER / INVOICE
☐ EVAPORATOR COIL						VOICE	61124	M OR PART DESCRIPTION	F VE (sel)		PRICE
☐ CLEAN COIL & CHECK FIN ☐ CONDENSATE AREAS					QUANTITY	The same of	Maria Maria	1	16		600.00
DINSPECT & CLEAN DRAIN PAN			-1		- 4	16	ean to	ireamly D	irty hil	,	666,66
☐ INSPECT & CLEAN DRAIN ☐ AIR FILTERS			1000		-	mal ;	e.		,	-	
O CLEANED D REPLACED		1/1	19								L
D HEATING ASSY. D BURNER & HEAT EXCHANGER FUEL SUPPLY & PRESSURE FILOT ASSEMBLY D FLAME AQUISTMENT D PRIMARY RELAY & FLUE FAN & UGHT SWITCH OPER. D BLOWER ASSEMBLY			Pa, 0	/	1	Clean	My Suj	plies			100.00
☐ ELECTRICAL COMPTS. ☐ RELAYS ☐ CONTACTORS ☐ OVERLOAD ☐ PRESS SWITCH											
THERMOSTAT DOK DREPLACE			FOANT							_	-
O RELOCATE	ENVIRONMENT	REFRIG	1	OTHER							
OPERATION DISCHARGE TEMP	RETURNED TO			onio.		1			TOTAL PART	S	100.00
D RETURN TEMP	THIS SYSTEM? DYE	es und al			-				SALES TA	X	
D TEMP DIFF.		ES DNO OT	Υ		1400	ň		383	LABO)R	1,00-00
***************************************			BOR		CHAR			HRS. ®	nn.		300-00
	DATE	MECH.	START	END					FREIG	нт	
- n (-		1			TO	TAL DUE UPON	RECEIPT	CFC RECOVE	RY	
☐ Refrigeration					PARTS	-		to take	SUB		
☐ Air Conditioning					LABOR	GUARANTEE The	charges as recorded here re s. We do not guarantee per the responsible for a labour	laine in the equipment services as it is other than those provided. If wars harge on this region, we service contri-	RO, S CUNT:		40
☐ Heating					COD of	less price arrangement in fell. Accounts 30 day	s have been made. J&H Ent is past due will be charged 1	l per manufacturer specifications Iddine to the equipment services data is other than those provided. If ware- morpe on this model, All words and equipment is model, All words and the equipment bodds the to all parts and the 1,02% per month. Oustomer may be	die for DUE		700.00
☐ Plumbing		-			lega fees	025451000	ing past due accounts. ASE PAY FROM Th			below 1	agree to the lenn's listed
☐ Kitchen Equipment						CHECK	242	CASH	Signature		To have
			1	1	1		2 64.11	100	Date	_	THANK YO

				T	M		&H ENT	TERPRI	SES			-
AKE						l out	OF MARC	QUETTE, LLC		DATE	19	12/24
ODEL#						374	OF MARC Kundê Hadisan Ri	d Skandia, N	M 49885	CUST.	10	0/54
RIALE					W	(906) 36	62-3956 jandl	h_enterprises	@yahoo	COIII		
CHECKLIST	DI	SCRIPTION OF V	ORK		OB LOC:					OUR P.O.#		
☐ COMPRESSOR	Install !	water D	16,100									
D SUCTION PSI D HEAD PSI D VOLTS AMPS D ELECTRICAL TO VNECTIONS	And all	HYPC	ols Re		BILLTO:	BP	Mark	4.		PHONE	1	
OIL LEVEL & CHECK FIN COND. CONDENSER COIL	14. to 161	11110		_1			V			ACCT.	#	_
CLEAN COR & CHECK FIN COND.	1114	-	1-1-1	6)	_					noo.		
FAN AND MOTOR O YOUTS AMPS CI ELECTRICAL CONNECTIONS OF FAN PULLEYS (ADJUST BELT)	100x VF	VAIL	Due to	0	-		(al			WORK	ORDER /	INVOICE
CHECK, LUBE BEARINGS & MOTOR	Canalition	1	With		INVOIC	E 5	2029				_	1770
EVAPORATOR COIL CLEAN COIL & CHECK FIN	Tange	50, 111	meil	5	QUANTITY			R PART DESCRIPT	ON			PRICE
CONDENSATE AREAS INSPECT & CLEAN DRAIN PAN	Cople	Holdili	final o	1400.00	L	max	nder F	Hon '	In. F	ial Big	1	0 167.6
AIR FILTERS	addd.				-		.1	1.1			r	2400,00
☐ CLEANED ☐ REPLACED ☐ HEATING ASSY.	c 1		e tirl	inst	6	14/10	itian	099	-	_	15	X TOUT
D BURNER & HEAT EXCHANGER D FUEL SUPPLY & PRESSURE D PILOT ASSEMBLY D FLAME ADJUSTMENT D PRIMARY RELAY & FLUE FAN & LIGHT SWITCH OPER BLOWER ASSEMBLY	Took to So poic	Of t	1	ayment	A	ddifi	iane (lost fo	or D	Ffirnce		200.00
D ELECTRICAL COMPTS. D RELAYS D CONTACTORS							- CAPEX!		HIN			
OVERLOAD OPRESS SWITCH THERMOSTAT							1.64	Must.				
D O.K. REPLACE		REFRIGE	RANT		-		- CHICK					
☐ OPERATION	ENVIRONMENT (CHECKLIST	OT	HER			1.	/		TOTAL PARTS	13	367.60
DISCHARGE TEMP RETURN TEMP	THIS SYSTEM? DYE					_	W			SALES TAX		
SUPERHEAT TEMP DIFF	REFRIG. TYPERECOVERED? DY				1 inon					LABOR		
			1		LABOR CHARGES			HRS.@	HR.			_
	DATE	MECH.	START	END						FREIGHT		
A WALLEY	DAIL					TOTAL	L DUE UPON RE	CEIPT	11.	CFC RECOVERY		
☐ Refrigeration					PARTS WARRA	NTY All parts as a	recorded are warranted per open as recorded here unlaring	manufacturer specifications to the contract of	ns. es as raied, is	SUB CONT:		
☐ Air Conditioning					guaranteed for a per	riod of 30 days. Wr customer will be re	e do not quarantes parts of esponsible for a labor charg	er than those provided on this repair All service	l warrady e calls ae	TOTAL	1.	4
☐ Heating					C.O.D. unless prior until paid in full. Acc legal fees associate	arrangements have ounts 30 days pas	recorded are warranted par ges as recorded here relative te do not quarrantee pails oth esponsible for a labor change we been made. J&H Emispris to due will be changed 1 1/29 past due accounts.	ses holds lite to all parts 6 per month. Customer o	and materials may be liable for	AMOUNT	13	367.6
☐ Plumbing					legal tees associate	A marray al	E PAY FROM THIS			By signing belo	w lagree t	to the terms listed
☐ Kitchen Equipment					Г	CHECK	CARD	☐ CASH		Signature		water or
		1			-		200			Dale		THANK YOU



NEW ADDRESS PLEASE UPDATE

Invoice

Date	Invoice #		
8/21/2024	11339		

1499 Enterprise Parkway Twinsburg, OH 44087 Phone: 216-398-8446 Fax: 216-398-8430

Toll Free:1-833-PAVE-CLE Sales@Advancedasphalipaving.com

Bill To	
Cross America Partners Gus Nicholson 600 Hamilton Street, Suite 500 Allentown, PA 18101	

Project	
BP	
32393 Lorain Rd	
North Ridgeville, OH 44039	
The same of the sa	

S.O. No.	P.O. No.	Terms
24-0314		
444	1	

Payments/Credits

Balance Due

\$0.00

\$59,863:00

Description	Amount
2" MILL & PAVE 30,082 SQ FT (ENTIRE LOT) Mill 30,082 square feet down (2.0") inches and haul material from job site. Clean & remove loose deteriorated pavement from surface areas and haul from job site. Apply a tack coat of SS-1 emulsion to ensure proper bond. Install a scratch leveling course of O.D.O.T. #448-1 asphalt at an average depth of (.5") inch and core or mitigate reflective cracking and stabilize existing surface prior to resurfacing. Install a surface course of O.D.O.T. #448-1 asphalt at an average depth of (1.5") inches after comparate course of O.D.O.T. #448-1 asphalt at an average depth of (1.5") inches after comparate stripe, per existing design. Striping shall include all ADA and mise, markings. Does not include and sidewalk paint. TOTAL = \$59,863.00 NOTE: INDIVIDUAL AREAS: Orange Area (11,028 Sq Ft) = \$23,600.00 Blue Area (9,452 Sq Ft) = \$23,600.00 Blue Area (9,602 Sq Ft) = \$23,833.00	on.
11/1/2	tal 050.042.00